

TYRE INSPECTION REPORT

 Company: THIESS/EASTERN TRACTORS

 Site: MT THORLEY

 Inspection date : 4/11/2021

 Veh. Make & type: CAT789B




 Fleet : RD1012

Hours : _____

Position	Size	Brand	Tread Spec	Serial Number	Original Tread (mm)	Remaining Tread (mm)	Tyre Condition	Rim / Wheel Number	Tyre Change Priority	Comments
1	42/90R57	B/S	VRDPY	S9S003715		75/76	A			OK
2	42/90R57	B/S	VRDPY	S9S004304		80/80	A			OK
3	37.00R57	B/S	VRLSA	S8K000659		75/75	A			OK
4	37.00R57	B/S	VRLSA	S7B005585		67/65	A			OK
5	42/90R57	B/S	VRDPY	S8J003126		50/62	C POOR			SIDEWALL CUTS AND DAMAGE
6	42/90R57	B/S	VRDPY	S8A003428		63/60	C POOR			SIDEWALL CUTS AND DAMAGE

TYRE CONDITION	
A	GOOD
B	FAIR
C	POOR

Tyre Change Priority	
Urgent	ASAP
Priority 1	Within 1 month
Priority 2	Within 2 months



Notes :

POS 1/2 TYRES OK
POS 5/6 THE WORST WITH SIDEWALL DAMAGE ON BOTH INSIDES OF TYRES
WITH POS 6 SIDEWALL CUTS TO OUTSIDE

POS 1

POS 2

POSITION 3/4

POS 5/6

POSITION 5/6 SIDEWALL DAMAGE

